PORST 11.3.25.1 v

LUBRIPLATE.

MATERIAL SAFETY DATA SHEET

PLATE Gear Shield Extra Heavy, Section 1 000698 Gear Shield Heavy, Gear Shield PRODUCT MAME OR MUMBER FORMULA LUBRIPLATE "Gear Shield" Series Lithium Soap, Mineral Oil and Additives Manufacturer's Name Emergency Telephone Number Fiske Brothers Refining Co. 201-589-9150 Telephone Number for Information 201-589-9150 Address Planton, Brest, City, State, and ZIP Code) 129 Lockwood St., Newark, NJ 07105 Section # - Hazardous Ingredients/Identity Information Other Limits Hazardous Components (Specific Chemical Identity; Common Name(s)) OSHA PEL ACGIH TLV Recommended % (optional) Non-hazardous Hazardous Material Identification System (HMIS): Health-1, Flammability-1, Reactivity-0 Section III - Physical/Chemical Characteristics Bolling Point Specific Gravity 840 - 1) > 550°F 0.95-0.98 Vapor Pressure (mm Ho.) Meting Point **<** 0.01 Semi-solid Density (AIR - 1) Evaporation Rate **>** 5 < 0.01 Butyl Acotato - 1) ickelly in Water Negligible Appearance and Odor Black grease with mineral oil odor Section IV — Fire and Explosion Hazard Data Flesh Point Blethod Used) Flammable Limbs coc - 400°F 7.0% 0.92 Extinguishing Media Foam, Dry Chemical, Carbon Dioxide or Water Spray (Fog) Special Fire Fighting Procedures Cool exposed containers with water. Use air-supplied breathing equipment for enclosed or confined spaces. Unusual Fire and Explosion Hazards Do not store or mix with strong oxidants. Empty containers retain residue. Do not cut, drill, grind, or weld, as they may explode. Section V — Reactivity Date Undable Conditions to Avoid STATE OF THE PERSON NAMED IN N/A Stable. Incompatibility (Materials to Avoid) Avoid contact with strong oxidants like liquid chlorine, concentrated oxygen. Your Decomposition or Byproducts
May form SO2. If incomplete combustion, carbon monoxide. Conditions to Avoid Mazardous May Occur **USEPA SF Polymerization** N/A Will Not Occur x 1265431

SECTION VI HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE 5 mg/m³ for oil mist in air. OSHA Regulation 29 CFR 1910.1000 EFFECTS OF OVEREXPOSURE Prolonged or repeated skin contact may cause skin irritation. Product contacting the eves may cause eye irritation. Human health risks vary from person to person. As a precaution, exposure to liquids, vapors, mists and fumes should be minimized. product has a low order of acute oral toxicity, but minute amounts aspirated into the

MRC Monographs? No NTP? Carcinogenicity: OSHA Regulated? No. EMERGENCY AND FIRST AID PROCEDURES EYE CONTACT: Flush with clear water for 15 minutes or until irritation subsides. If irritation persists, consult a physician. SKIN CONTACT: Remove any contaminated clothing and wash with soap and warm water. If injected by high pressure under skin, regardless of the appearance or its size, contact a physician IMMEDIATELY. Delay may cause loss of affected part of the body. INHALATION: Vapor pressure is very low and inhalation at room temperature is not a problem. If overcome by vapor from hot product, immediately remove from exposure and call a physician. INCESTION: If incested, call a physician immediately. Do not induce vomiting.

SECTION VII SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

lungs during ingestion may cause mild to severe pulmonary injury.

Scrape un grease, wash remainer with suitable petroleum solvent or add absorbent. Keen petroleum products out of sewers and water courses. Advise authorities if product has

entered or may enter sewers and water courses

WASTE DISPOSAL METHOD ssure conformity with applicable disposal regulations. Dispose of absorbed material at

an approved waste disposal facility or site.

SARA/TITLE III, Section 313 Status - Zinc Compounds - (5% of Zn)

SECTION VIII SPECIAL PROTECTION INFORMATION RESPIRATORY PROTECTION (Specify type) Normally not needed			
	MECHANICAL (General)		OTHER
PROTECTIVE GLOVES Use pil-resistant gloves, if needed.		If chance of	eye contact, wear goggles.
OTHER PROTECTS		nyon if nooded	

SECTION IX SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Do not handle or store near heat, sparks, flame, Geen containers closed when not in use.

strong oxidants.

OTHER PRECAUTIONS

Remove oil-soaked clothing and launder before reuse. Clean.

skin thoroughly after contact.

DATE PREPARED January 1992

PREPARED BY: Robert J. Sibilia